



TRANSITION FITTING PE/ BRASS



male thread

PE100



SDR 11



Art. No.	d1 [mm]	R [mm]	le1 [mm]	L [mm]	z1 [mm]	kg
4450421100630112	63	1??"	100	190		0,80

For questions, please feel free to contact us at: Tel. + 49 281 98 414 - 0